


A photograph of a steep, eroded slope. A dirt path leads up the center of the slope. The slope is covered with green grass and some small yellow flowers. At the top of the slope, there is a dense line of evergreen trees. In the foreground, there are large, dark grey rocks.

March 13, 2013

Vantreight Slope





Note tree for reference

December 8, 2014

Ivy Removal



December 8, 2014

Ivy Removal





December 9, 2014



First row of wattle fences



December 9, 2014



Going up



December 12, 2014

Getting to the steep part.






December 12, 2014



Nearing the top.






Reference Tree

December 15, 2014

Almost done.





Reference Tree

December 15, 2014

Top completed.





December 15, 2014

Slope completed

